Software Defined Radio with Zynq® UltraScale+ RFSoC

Errata

Book first published January 2023.

Revision I, June 2025.

Changes / corrections made in this revision:

- 1. Equation 2.1 for Free Space Path Loss was corrected, and given in terms of decibels (dB).
- 2. Figure 9.14 showed incorrect information, and was replaced with a new diagram. (Secondarily, some changes to text flow resulted, as this diagram was larger than the original.)
- 3. Figure 9.16 was replaced. Originally this showed the magnitude response for FIR1, but it should have shown the magnitude response for FIR2.
- 4. The text under Table 9.3 was amended to reflect that only the filters decimating by a factor of 2, i.e. the FIR4, FIR3, FIR2, and FIR1a filters, are halfbands (the others pass 1/3 and 1/5 of the band, respectively, therefore cannot be halfbands).
- 5. Figure 9.23 was amended. The 'IF' and 'RF' labels in the bottom diagram were swapped.
- 6. Table 9.5 was moved to the bottom of page 330, underneath Figure 9.28, such that the example follows all of the related technical information.
- 7. Various small typographical changes in Chapter 9.